



Changes are needed to the Waihi Beach Dam to meet dam safety regulations. The dam provides little benefit in a large rainfall event.

Council is assessing options on removing the dam and upgrading One Mile Creek to ensure that flooding is not made worse and if possible improve the performance.

One Mile Creek has several sharp bends making it prone to erosion and instability. The fast flowing water can create a hazardous area for the properties downstream of the dam.

The Beach Road culvert is not designed to allow large flows and needs to be upgraded.

Waihi Beach Dam

One Mile Creek Inlet

One Mile Creek Outlet

Produced using ArcMap by the Western Bay of Plenty District Council GIS Team.  
 Crown copyright reserved. LINZ digital license no. HN/352200/03 & 10095522.  
 Location of services is indicative only. Council accepts no liability for any error.  
 Archaeological data supplied by NZ Archaeological Assoc./Dept. of Conservation.

Email: gis@westernbay.govt.nz  
 Date: 12/02/2025  
 Operator: sio  
 Map: WaihiBeach\_Stormwater

